

CARDONE ProTech

Supporting Today's Professional Technician




In-Line Power Steering Filter — An Ounce of Prevention

Application: All power steering equipped vehicles.

Problem: Premature failure of power steering components.

Cause: Particles not removed during the flushing process or particles from everyday wear of components and hoses cause valves to stick and block fluid flow.

Solution: When replacing any power steering component always thoroughly flush the entire system and install a CARDONE Power Steering Cartridge-style Filter (20-FLT1) or Transmission-style filter (20-FLT2).



Note: Always use the fluid recommended by O.E. for your vehicle.

For other ProTech publications, visit www.cardone.com
CARDONE Industries, Inc. • 5501 Whitaker Ave. • Philadelphia, PA 19124-1799