



**CARDONE**<sup>®</sup>  
*Select*

# **CARDONE Select** **Power Steering Pump** **Provides Supply Solution**

## **CARDONE Select 96-286 Power Steering Pump for 1999-2003 Ford Windstar V6 with 3.8L Engine**

**Problem:** High failure rates and O.E.M. supply shortages leave few options for replacement units.

**Solution:** Capitalizing on decades of experience in steering remanufacturing, CARDONE provides a TOTALLY NEW solution to the problem. Utilizing CARDONE Select Engineered (CSE) Technology, we have eliminated O.E.M. design flaws and offer a pump that meets the highest quality and endurance standards in the industry.

### **The CARDONE Select 96-286 Power Steering Pump features:**

- **Precise bushing alignment** – Prevents premature wear of the shaft and seal, significantly reducing noise and vibration.
- **Upgraded shaft, rotor and camring steel** – Produces a quieter, more durable pump than the O.E.M. design.
- **Internal redesign of campac to tighter tolerances** – Provides increased efficiency of the pump and allows optimal flow and pressure at all RPM ranges of pump operation.
- **Manufactured with premium grade, high-temperature seals** – Added durability in sealing area under normal and extreme driving conditions.
- **100% computerized testing performed at load** – Ensures the optimal performance and durability by incorporating real-world parameters during the test cycle of the pump.

By offering a NEW alternative to this hard-to-find application, CARDONE provides another solution to help drive your business.

**Silent performance**  
**over the long haul.**

[www.cardone.com](http://www.cardone.com)

