

CORE POLICY AND DEDUCTION

EGR COOLERS

50% LESS CREDIT

- Dented coolant tube
- EGR delete kit installed
- Broken or bent mounting bracket
- Missing mounting threads
- Dented outer housing



All cores must be returned in the original box to receive full core credit.

All cores not returned in the box receive maximum 10% core credit.

Core credit allowed only for units in the current programs.

Only exchange cores accepted for core credit.