

CARDONE ProTech

Supporting Today's Vehicle Technician




Distributor Replaced: Check Engine Light Still On

Application Most OBDII equipped vehicles (1995 and newer).

Problem Check engine light still on after distributor replacement.

Cause Original trouble code was not cleared from the computer.

Solution On some vehicles, permanent stored trouble codes must be manually cleared. After distributor replacement, if codes remain (check engine light still on), they must be erased using a suitable scan tool. Refer to your vehicle's service manual for proper procedures.



For other ProTech publications, visit www.cardone.com