

CORE POLICY AND DEDUCTION

HYBRID DRIVE BATTERIES

NO CORE CREDIT

- Tampered with or incorrect high voltage modules

75% LESS CREDIT

- Missing or damaged high voltage modules

50% LESS CREDIT

- Heavily bent or missing sheet metal

25% LESS CREDIT

- Moderately bent or rusted sheet metal
- Missing or damaged battery ECU
- Missing or damaged battery relays
- Unit returned without original packaging
- Missing or damaged blower fan



All cores must be returned in the original box to receive full core credit.

All cores not returned in the box receive maximum 10% core credit.

Core credit allowed only for units in the current programs.

Only exchange cores accepted for core credit.