

CORE POLICY AND DEDUCTION

POWER STEERING GEARS

NO CORE CREDIT


- Housings that are worn, broken, cracked or rusted
- Disassembled units

50% LESS CREDIT

- Broken or missing input valve assembly

10% LESS CREDIT

- Broken sector shaft



All cores must be returned in the original box to receive full core credit.

All cores not returned in the box receive maximum 10% core credit.

Core credit allowed only for units in the current programs.

Only exchange cores accepted for core credit.