

## Distributor Replaced: Check Engine Light Still On

**Application** Most OBDII equipped vehicles (1995 and newer).

Solution

**Problem** Check engine light still on after distributor replacement.

Cause Original trouble code was not cleared from the computer.

On some vehicles, permanent stored trouble codes must be manually cleared. After distributor replacement, if codes remain (check engine light still on), they must be erased using a suitable scan tool. Refer to your vehicle's service manual for proper procedures.



©2020 CARDONE Industries, Inc. ProTech® is a registered trademark owned by CARDONE Industries, Inc. CARDONE™ is a pending trademark registration owned by CARDONE Industries, Inc.

DSA6311 PT30-0005